

Message

---

**From:** Sam Waldo [SWaldo@amphenol.com]  
**Sent:** 11/16/2015 7:58:19 PM  
**To:** Thomas, Juan [thomas.juan@epa.gov]  
**Subject:** Franklin, IN  
**Attachments:** Phase I Data Evaluation Report\_September 17 2007.pdf

Juan,

Per our conversation.

As we discussed, based on our investigations reported in this Phase 1 report, we did not then, nor do we now, believe that a plume from the Former Amphenol facility in Franklin is affecting the water company well field or even migrating in the general direction of those wells. At the end of our meeting with USEPA and the water company on November 27, 2007, USEPA indicated that, after reviewing the attached report, they would respond to the conclusions contained in that report.

I've asked IWM to provide me with links to several reports prepared by IDEM which conducted its own investigation and determined that the former Houghland Tomato Cannery is the suspected source area of the Webb Well Field contamination. That facility and its buildings are no longer in existence but they were located upgradient and to the northeast of the former Amphenol facility and NNW and directly upgradient of the well field. We also understand that all of the IDEM reports (the latest of which was generated in early 2015) indicate that the two Indiana American Water Wells that had historical detection of HVOCs are out of service and would only be used in an emergency. As I indicated in our phone call, Google Earth photos indicate that water treatment equipment, which was previously present at the well field, has been completely removed from the site.

As soon as I get the links mentioned above I will forward them to you.

Regards,

Sam

Samuel S. Waldo  
Director, EHS & Support Services  
Amphenol Corporation  
(203)265-8760 (o)  
(203)605-3786 (m)  
(203)265-8746 (f)  
swaldo@amphenol.com